







- WCP ENVELOPE**  
A DIVISION OF WCP SOLUTIONS
- Please follow the exact die lines. It is important to keep the scale at 100%.
  - It is essential that the grain run in the direction specified.
  - The position of the envelope is critical to insure proper breakout in the die cutting process.
  - Minor variations may occur in the die cutting and folding process. For best results, follow our layout.
  - Envelope machines cannot fold perfect borders or bleeds. Designs with bleeds must wrap 1/8" around to back.
  - This envelope may not be suitable for solid coverage envelopes where the ink extends beyond the cut lines. If you are running a full bleed, please add gripper and color bar dimensions to the sheet size.
  - Please mark your guide and gripper. Make sure that the stock is logged.
  - Knockout areas must be free of ink and varnish; otherwise glue or gum may fail.
  - Please call if you require a special layout for knockouts.
- Thank you.




- WCP ENVELOPE**  
A DIVISION OF WCP SOLUTIONS
- Please follow the exact die lines. It is important to keep the scale at 100%.
  - It is essential that the grain run in the direction specified.
  - The position of the envelope is critical to insure proper breakout in the die cutting process.
  - Minor variations may occur in the die cutting and folding process. For best results, follow our layout.
  - Envelope machines cannot fold perfect borders or bleeds. Designs with bleeds must wrap 1/8" around to back.
  - This envelope may not be suitable for solid coverage envelopes where the ink extends beyond the cut lines. If you are running a full bleed, please add gripper and color bar dimensions to the sheet size.
  - Please mark your guide and gripper. Make sure that the stock is logged.
  - Knockout areas must be free of ink and varnish; otherwise glue or gum may fail.
  - Please call if you require a special layout for knockouts.
- Thank you.



- WCP ENVELOPE**  
A DIVISION OF WCP SOLUTIONS
- Please follow the exact die lines. It is important to keep the scale at 100%.
  - It is essential that the grain run in the direction specified.
  - The position of the envelope is critical to insure proper breakout in the die cutting process.
  - Minor variations may occur in the die cutting and folding process. For best results, follow our layout.
  - Envelope machines cannot fold perfect borders or bleeds. Designs with bleeds must wrap 1/8" around to back.
  - This envelope may not be suitable for solid coverage envelopes where the ink extends beyond the cut lines. If you are running a full bleed, please add gripper and color bar dimensions to the sheet size.
  - Please mark your guide and gripper. Make sure that the stock is logged.
  - Knockout areas must be free of ink and varnish; otherwise glue or gum may fail.
  - Please call if you require a special layout for knockouts.
- Thank you.



- WCP ENVELOPE**  
A DIVISION OF WCP SOLUTIONS
- Please follow the exact die lines. It is important to keep the scale at 100%.
  - It is essential that the grain run in the direction specified.
  - The position of the envelope is critical to insure proper breakout in the die cutting process.
  - Minor variations may occur in the die cutting and folding process. For best results, follow our layout.
  - Envelope machines cannot fold perfect borders or bleeds. Designs with bleeds must wrap 1/8" around to back.
  - This envelope may not be suitable for solid coverage envelopes where the ink extends beyond the cut lines. If you are running a full bleed, please add gripper and color bar dimensions to the sheet size.
  - Please mark your guide and gripper. Make sure that the stock is logged.
  - Knockout areas must be free of ink and varnish; otherwise glue or gum may fail.
  - Please call if you require a special layout for knockouts.
- Thank you.



Grain Direction